

## THE NATIONAL BOARD

OF

BOILER & PRESSURE VESSEL INSPECTORS

## Certificate of Authorization



This is to certify that Ingesol Latinoamerica Ltda. Calle 2 Lote 2 Giron, Santander Colombia

is authorized to use the R Symbol in accordance with the provisions of the National Board Inspection Code and NB-415, Accreditation of "R" Repair Organizations.

All activities within the scope of this Authorization shall be controlled by the above location.

The scope of this Authorization is limited to:

Metallic Repairs and Alterations At Shop and Field Locations

Certification Number:

Issue Date: Expiration Date:

**Executive Director** 

10720

January 18, 2024 December 18, 2026